



RhinoMite™ Two-Part Adhesive

RhinoMite™ Adhesive systems offers high tensile strength, impact and solvent resistance. Both dry in approximately 10 -15 minutes. Once mixed, they have a pot life of seven or more days. Each unit is shipped as a kit with catalyst.

RMA 3000 Thick	
Weight Solids:	19%
Viscosity :	100 - 300 cPs
Weight / Gallon:	10.9 - 11.1 lbs.
Color :	Amber or Red
Solvents:	Methylene Chloride
Shelf Life:	6 months unopened
Package Size:	Quart or Gallon Plus Catalyst

RMA 3000 Thin	
Weight Solids:	17%
Viscosity :	100 - 300 cPs
Weight / Gallon:	10.9 - 11.1 lbs.
Color :	Amber or Red
Solvents:	Methylene Chloride
Shelf Life:	6 months unopened
Package Size:	Quart or Gallon Plus Catalyst

RMT 3001 Thinner	
Package Size :	Quart or Gallon

RMC-4 Catalyst	
Package Size :	2 ounces

RMA 2990 Thin	
Weight Solids:	15%
Viscosity :	100 - 300 cPs
Weight / Gallon:	10.9 - 11.1 lbs.
Color :	Amber or Red
Solvents:	Acetone
Shelf Life:	6 months unopened
Package Size:	Quart or Gallon Plus Catalyst
RMC-8	4 ounces

RMA 3500	
Viscosity :	100 - 300 cPs
Weight / Gallon:	10.9 - 11.1 lbs.
Color :	Red
Solvents:	1.3 Dioxolane
Shelf Life:	6 months unopened
Package Size:	Quart or Gallon Plus Catalyst

RMT 3501 Thinner	
Package Size :	Quart or Gallon

RMC-4 Catalyst	
Package Size :	2 ounces

Mixing:

The RMC 4 Catalyst with RhinoMite using these ratios:

- 2oz. Catalyst to 1 Gal. RhinoMite
- 1/2oz. Catalyst to 1 Qt. RhinoMite
- 1/4oz. Catalyst to 1 Pt. RhinoMite

Pot life is 3 to 5 days / Store in closed container.

Fine Mesh:

You should thin the adhesive to insure good penetration through the fabric. It is recommended that 10% to 20% thinner (RMT3001 / RMT3501 be added after the adhesive has been catalyzed.

Best Results:

1. Prime Aluminum frames and let dry.
2. Stretch fabric in contact with frame.
3. Apply adhesive / a short nap brush works best, as is it will push the adhesive thru the mesh or you can use a plastic spreader.
4. Allow the adhesive to dry for 10-12 minutes. Humidity & Temperature along with the thickness of the adhesive will effect the drying time.
5. Remove the frame from the stretcher.
6. All of these types of adhesive cure over 24 hours.

PO Box 5426 Sarasota, FL 34277
Tel: 651-686-5027 Fax: 651-686-9745
e-mail: info@rhinotechinc.com
web page: www.rhinotechinc.com